



Connecting to the IV Curve Tracer

Step 1: Select the COM port the IV Curve Tracer is using.



Step 2: Connect to the IV Curve Tracer using the Connect/Disconnect Menu.



Step 3: Verify the IV Curve Tracer is connected using the status bar icon.

