


Male Swivel Joint

1 1/2" 90° PVC Elbow



Step #1


Male Swivel Joint

Step #2

Servo Mount Elbow Clamp (printed part)
Secure with 4-40 x 3/4" Round Head Screw.
Will need to be positioned such that servo
arm lines up with ball joint on vertical pipe

2" Tie Rod

2 1/4" Tie Rod



Servo Mount Elbow Clamp (printed part)
Secure with 4-40 x 3/4" Round Head Screw.
Will need to be positioned such that servo arm lines
up with ball joint on Rotational Bearing Assembly

Use Straight Servo
Horn Shown (2X)

Attach servo with screws
provided in servo kit

