

BATTERY BANK FOR SOLDERLESS BREADBOARD

INPUT: 5V 500mA  
OUTPUT: 5V 1000mA

BATTERY INDICATOR: GREEN 50-100%  
YELLOW 20-50%  
RED 0-20%

ALWAYS LEAVE POWER OFF WHILE CHARGING.

BATTERY BANK FOR SOLDERLESS BREADBOARD

INPUT: 5V 500mA  
OUTPUT: 5V 1000mA

BATTERY INDICATOR: GREEN 50-100%  
YELLOW 20-50%  
RED 0-20%

ALWAYS LEAVE POWER OFF WHILE CHARGING.

