

* For the blade's to be first engraved I used an engraving bit and set the depth to .15 and the RPM to 3000.
To cut I used a 1/8 bit, RPM 3000 and feed rate was set to 30%

